



Blackfin Sportfish Engine Compartment:

We were contacted about an engine noise issue in a Blackfin Sportfish 31. A combination of Acoustiblok® and Starboard was installed in the engine compartment lid. Customer stated "The piercing turbo whine was reduced over 30%. The Blackfin is now a greatly improved boat and is much quieter – Acoustiblok® really does work."



Blackfin SportFish Combi 31'




Completed engine lid



Engine lid with furring strips



Starboard covering (template)



Starboard with Acoustiblok®



Installed Starboard

1965 Bertram Boat:

We were contacted to resolve an engine noise issue in a 1965 Bertram boat. Acoustiblok® was applied to the engine compartment, lid and adjacent areas. The noise reduction that resulted allowed people to have conversations on the boat while at speed on the water. The 79 years old customer has been restoring boats for many years and said that Acoustiblok® is the best sound barrier he has used.



1965 Bertram boat



Completed engine compartment



Before installation



After Acoustiblok® application



Before installation



After Acoustiblok® application

Jet Boat Engine Compartment:

Before installing Acoustiblok®



After installing Acoustiblok®



We were contacted by an individual to resolve a noise issue with a Jet Boat engine. Acoustiblok® was used to line the engine compartment and the engine bay lid. After installation the customer stated a significant reduction and could actually have conversations on the boat at 25mph!!

